

DC Converter


Sold 4 wires on copper side at pins:

12V+ (power input)

12V- (power ground)


D (High Voltage output)

B (High Voltage ground)



Secure the DC converter to the PCB using

- Hot glue
- or glue
- or double side tape



Sold the 4 wires on the PCB

